# LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

## Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021** Time Collected: **8:18am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg A - 2<sup>nd</sup> Floor - Kids Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192111

Parameter/Method	Limit	Result
Lead (SM 3113B)	0.015 mg/L	0.0033 mg/L
Copper (SM 3111B)	1.30 mg/L	<0.10 mg/L
>= greater than <=	· less than	

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021

## LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

# Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021** Time Collected: **8:21am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg A - 1st Floor - Adult Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192112

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	<0.002 mg/L
Copper (SM 3111B)		1.30 mg/L	<0.10 mg/L
>= greater than	< = less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021

**Donald B. Lilley**By: \_\_\_\_\_

Donald B. Lilley/Director

# LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

# Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021** Time Collected: **8:23am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg A - 1st Floor - Kids Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192113

Parameter/Method	Limit	Result
Lead (SM 3113B)	0.015 mg/L	0.0126 mg/L
Copper (SM 3111B)	1.30 mg/L	<0.10 mg/L
>= greater than <=	= less than	

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021

# LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021** Time Collected: **8:27am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg B - 1st Floor - Kids Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192114

Parameter/Method		Limit	Result
Lead		0.015 mg/L	0.0036 mg/L
(SM 3113B)  Copper (SM 3111B)		1.30 mg/L	<0.10 mg/L
	< = less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021

# LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

# Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021**Time Collected: **8:29am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg B - 1st Floor - Adult Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192115

Parameter/Method	l	Limit	Result	
Lead (SM 3113B)		0.015 mg/L	0.0091 mg/L	
Copper (SM 3111B)		1.30 mg/L	0.143 mg/L	
>= greater than	<= less than			

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021

# LECO LABORATORY

3123 Klockner Road Trenton, New Jersey 08690 Laboratory I.D. # NJ11106

Mill Hill Child & Family Development 101 Oakland Street Trenton, NJ

Date Collected: **4-29-2021** Time Collected: **8:32am** 

Matrix: Water

Source: Church Child Care Area

Point of Collection: Bldg B - 2<sup>nd</sup> Floor - Kids Sink

Sampled by: Owner

Analysis By: Certified Lab ID # NJ03886

LECO Sample #: L1192116

Parameter/Method		Limit	Result
Lead (SM 3113B)		0.015 mg/L	0.0068 mg/L
Copper (SM 3111B)		1.30 mg/L	<0.10 mg/L
>= greater than	< = less than		

Remarks:

Both parameters tested meet the requirement established by the NJDEP.

Date: May 21, 2021